
Smoke and Dye Testing Summary

High Level Sewershed

Run Summary

Test ID	Test Type	Date Inspected	Company / Super.	Blower MH	Ground Condition	Notification Made?	Total Length
S1028-061	Smoke	9/3/2008	ADS/TM	S09EE1011MH	Dry	Yes	1,638.67

Isolated Pipes

Pipe ID	Upstream MH	Downstream MH	Length (ft)	Diameter (In)
S09EE1001G1	S09EE1001MH	S09GG1001MH	342.3103	8
S09GG1001G1	S09GG1001MH	S09EE1023MH	275.544	8
S09EE1023G1	S09EE1023MH	S09EE1019MH	241.3693	8
S09EE1026G1	S09EE1026DE	S09EE1019MH	123.9773	8
S09EE1019G1	S09EE1019MH	S09EE1011MH	70.15191	8
S09EE1011G1	S09EE1011MH	S09EE1018MH	249.8503	8
S09EE1027G1	S09EE1027UN	S09EE1003MH	335.4622	8

Observations & Photos

Obs_ID S1028-061-OB01

Address 3319 Cold Spring Lane

Status Private

Source Cleanout

Location Paved concrete

Nearest MH S09EE1001MH

Comments Smoke from cleanout in front parking lot. 3319 Cold Spring Lane



Picture \S1028-061-OB01-P01.jpg

Comments Front of building, 3319 Cold Spring Lane

Obs_ID S1028-061-OB02

Address 3315 Cold Spring Lane

Status Private

Source Cleanout

Location Paved asphalt

Nearest MH S09EE1001MH

Comments Smoke from cleanout in front lot of building. 3315 Cold Spring Lane



Picture \S1028-061-OB02-P01.jpg

Comments Front of building, 3315 Cold Spring Lane